Release Note for Vigor2952 Series

Firmware Version:	3.8.9.1
Release Type:	Normal
Applied Models:	Vigor2952, Vigor2952P, Vigor2952n, Vigor2952Pn

Vigor2952 is a broadband router with dual-WAN interface. It provides policy-based load-balance, fail-over and BoD (Bandwidth on Demand), also it integrates IP layer QoS, NAT session/bandwidth management to help users control works well with large bandwidth.

New Features

● None.

Improvement

● Corrected: The settings in APP Enforcement Profiles were messed up, after upgrading the firmware to Version 3.8.9.
  Suggestion: Choose one of the following methods to upgrade the router firmware.
  - Upgrade the firmware from the old version to new version (V3.8.9.1) directly.
  - Upgrade the firmware to V3.8.9 by using "x.all". Do not modify the APP profile configuration and then upgrade the firmware to 3.8.9.1.

● Corrected: When enabling Data Flow Monitor, Bandwidth Limit and Dynamic DNS Setup, the system would reboot after logging into web user interface.

● Corrected: Vigor router reboot randomly due to incompliant with TR-069 server.

Known Issue

● None.

RD NO: 107_06_12