Release Note for Vigor300B

Firmware Version:	1.5.1.1
Release Type:	Critical
Applied Models:	Vigor300B

Vigor300B, a firewall broadband router with the multi-WAN interface, can connect to xDSL/cable/VDSL2/Ethernet FTTx. The multi-WAN and LAN switch facilitates unified communication applications in business CO/remote site to handle large data from the subscribed fatter pipe. The state-of-art routing feature and multi-WAN provide integrated benefits for professional users and small offices.

This is a critical update - You should upgrade such Vigor router immediately with firmware containing these improvements.

New Features

- None.

Improvement

- Improved: Improved WebGUI security.
- Improved: Disable the local/remote port forwarding via SSH.
- Improved: Special character (e.g., `) is not allowed to use for User Profile.
- Corrected: An issue of unable to access WUI due to some reasons.
- Corrected: An issue of getting NTP time after the system reboot.
- Corrected: An issue that some outgoing TCP Packets were not NATed.
- Corrected: An issue that IP Bind Mac table could not be sorted alphabetically, correctly.
- Corrected: An issue of taking long time to display the main page after login.
- Corrected: An issue of failing to apply for Let's Encrypt certificate when Web Allow was disabled.

Known Issue

- None.