Release Note for Vigor300B

Firmware Version:	1.5.1.3
Release Type:	Normal
Applied Models:	Vigor300B

Vigor300B, a firewall broadband router with the multi-WAN interface, can connect to xDSL/cable/VDSL2/Ethernet FTTx. The multi-WAN and LAN switch facilitates unified communication applications in business CO/remote site to handle large data from the subscribed fatter pipe. The state-of-art routing feature and multi-WAN provide integrated benefits for professional users and small offices.

New Features

- None.

Improvement

- Improved: Web GUI Security.
- Improved: Update DNSMASQ for improving CERT/CC and CISA Report in DNSMASQ (VU#434904 / ICSA-21-019-01)
- Corrected: An issue of downloading Lets Encrypt certificate.
- Corrected: An issue of unusual Syslog entries for root password.
- Corrected: A display error issue after performing the Auto Firmware Upgrade.
- Corrected: An issue that disabled SNMP was re-enabled after router's system reboot.
- Corrected: An issue of "Let's Encrypt certificate" not being responded to by the router.
- Corrected: An issue of 2FA via mail through WAN not working if WAN port was configured as Static.

Known Issue

- None.