Release Note for Vigor3100 Series

Firmware Version: 2.8.6
Built Date: January 13, 2012
Applied Models:
Vigor3100/ Vigor3100V/Vigor3100i/Vigor3120

New Features

- None

Improvement

- Fixed: MiniVigor USB device plugged caused reboot issue.

Known Issue

- None

Notes

- Firmware (SHDSL) version marked with R4.31: Standard
- Firmware (SHDSL) version marked with R3.11: For old DSLAM compatible.