Release Note for VigorAP 1000C

Firmware Version:	1.4.5
Release Type:	Normal
Applied Models:	VigorAP 1000C

VigorAP 1000C is a ceiling-mount Wi-Fi for business networks. As a tri-band AP, it provides an extra 5GHz Wireless band which increases the supported number of wireless devices. In Mesh mode or Range Extender mode, this extra band can also be dedicated as the Uplink band to the Internet. VigorAP 1000C is suitable to construct a small Wireless network.

New Features

● Add the new feature of event alert (Diagnostics>>Alert Event).

Improvement

● None.

Known Issue

● System performance will drop when Bonding is enabled.
● Web access via HTTPS doesn't work well after the firmware upgrade. It is recommended to use HTTP instead or use either of the methods below to fix this problem temporarily.
   (a) Enable "Enforce HTTPS Access" on web System Maintenance >> Management.
   (b) Use "https://{IP}/login.asp" to access web. (Add "/login.asp" manually after IP. For example: "https://192.168.1.11/login.asp")

Note

● The throughput figures are maximum, based on DrayTek internal testing with optimal conditions. The actual performance may vary depending on the different network conditions and applications activated.