Release Note for VigorAP 800

Firmware Version: 1.1.2
Release Date: October 30, 2013
Applied Models: VigorAP 800

With this high cost-efficiency VigorAP 800, computers and wireless devices which are compatible with 802.11n can connect to existing wired Ethernet network via this VigorAP 800, at the speed of 300Mbps. Easy install procedures allows any computer users to setup a network environment in very short time - within minutes, even inexperienced users.

New Features

- None.

Improvement

- Fixed: Schedule profile cannot be deleted.
- Fixed: Universal Repeater mode cannot work with specific DHCP server.
- Fixed: Stability problem for AP management.
- Improved: The management port is adjustable.
- Improved: To keep Wi-Fi radio alive, a message of "hello" can be sent to iPad on UDP port (5353) per 5 seconds.
- Improved: The characters of "|\;'<>.?/" can be used in user name and password.

Related Information

- Get the document, please visit
  http://www.draytek.com/user/PdInfoDetail.php?Id=122

- Get the new firmware, please visit
  http://www.draytek.com/user/SupportDownloads.php

- Get the customer service support, please visit
  http://www.draytek.com/user/ContactHeadquarters.php

- Get the regulatory compliance information
  http://www.draytek.com/user/AboutRegulatory.php

- Get information for global partners

http://www.draytek.com/user/Globalpartners.php

Known Issue

- None

Notes

Modifications

- None