Release Note for VigorFly 200 Series

Firmware Version: 1.3.3
Release Date: January 21, 2015
Applied Models:
VigorFly 200

VigorFly 200 is a compact broadband router with 802.11n WLAN network. Its Ethernet WAN port can connect to VDSL/VDSL2/GPON/G.SHDSL /ADSL2+/ADSL/cable modem while you have fixed line. The NAT throughput can easily manage time-critical multimedia streaming. It's easy for family or friends to hook up PCs via embedded 10/100 Ethernet LAN switch to enjoy multimedia applications. Two antennas provide you with speedy WLAN networking. If you are out of coverage of fixed line, you can directly plug 3.5G USB modem to USB port on VigorFly 200.

New Features

- Add TR-069 parameters for account and password

Improvement

- Corrected: Disable "Auto Firmware Upgrade" due to MITM attack security.
- Improved: Remove the drop down list for the WDS Phy Mode option on **Wireless LAN(2.4GHz)>>General Setup**.
- Corrected: DHCP server offered service for the request which is not its own.
- Corrected: MAC information on Syslog was disappeared when a Wi-Fi client connected to VigorFly210 by WPA2/PSK.
- Corrected: With the feature of External Device offered by Vigor router (e.g, Vigor2860), the external device status would not display correctly by unplugging and plugging VigorFly from and onto Vigor router.
- Improved: Enhanced for SSLv3 Fallback protection.
- Improved: After rebooting, VigorAP can not auto update time from NTP server.
- Improved: Daylight saving is incorrect for AU and NZ.
- Improved: After pressing **OK** button on **Wireless LAN >> General Setup**, WAN will reconnect.

Known Issue

- None

Notes

Modifications

- None