Release Note for VigorSwitch P1092

Firmware Version:	1.04.07
Release Type:	Normal
Applied Models:	VigorSwitch P1092

VigorSwitch P1092, a standard switch, meets both IEEE 802.3u/ab Fast Ethernet and Gigabit Ethernet specifications.

New Features

- Add the function of port isolation.

Improvement

- Improved: Improvement of Port Loop Prevention.
- Improved: Modify the mechanism of managing packets of Smart Lite.

Known Issue

- None.

Note

- Reset VigorSwitch device after upgrading the firmware. To take advantage of the improved Loop Prevention algorithm, it is necessary to factory reset the VigorSwitch after updating to the 1.04.07 firmware. This step is optional; without a reset the switch will function normally but won't offer the updated port loop prevention algorithm.