

Release Note for Wireless APP (iOS)

Firmware Version:	1.3.6
Release Type:	Regular – Upgrade recommended when convenient, as it includes general improvements and optimizations
Applied Models:	See below

DrayTek Wireless APP is an ideal mobile application for on-premises Vigor router / AP configuration and monitoring. It allows you to easily configure and manage the Mesh Wireless network with the following key benefits:

- Intuitively and easily set up a Vigor Mesh group from scratch
- Scan and sync configurations automatically to newly added VigorAPs
- Basic configuration for WiFi name / password, channel, admin password, TR-069 and etc
- Monitor the Mesh node (APs) for WiFi signal strength and topology
- Monitor WiFi clients with device names, signal strength, real-time data rates and etc

New Features

- None.

Improvement

- Corrected: An issue where VigorAP 1070C could not register with the APP and the system displayed a "Network Failure" message.
- Corrected: An issue where the system crashes when opening Wireless APP > Diagnostic once after upgrade the mobile system to iOS 26.0.
- Corrected: An issue where the Register button was not displayed under APP > Push Notification Setting when trying to register AP1070C or AP1062C with the APP.

Known Issue

- None.

Applied Model

- VigorAP 802 (with firmware 1.4.1 and above)
- VigorAP 805 (with firmware 5.0.5 and above)
- VigorAP 903 (with firmware 1.4.1 and above)
- VigorAP 905 (with firmware 5.0.4 and above)

- VigorAP 906 (with firmware 1.4.6 and above)
- VigorAP 912C (with firmware 1.4.1 and above)
- VigorAP 918R (with firmware 1.4.0 and above)
- VigorAP 920R (with firmware 1.4.0 and above)
- VigorAP 960C (with firmware 1.4.0 and above)
- VigorAP 962C (with firmware 5.0.5 and above)
- VigorAP 1000C (with firmware 1.4.0 and above)
- VigorAP 1060C (with firmware 1.4.0 and above)
- VigorAP 1062C (with firmware 1.5.3 and above)
- VigorAP 1070C (with firmware 5.1.0 and above)
- Vigor2765 Series (with firmware 4.3.1 and above)
- Vigor2862ac/Vac/Lac (with firmware 3.9.5 and above)
- Vigor2865 Series (with firmware 4.2.2 and above)
- Vigor2926ac/Vac/Lac (with firmware 3.9.5 and above)
- Vigor2927 Series (with firmware 4.2.4 and above)

Note

- Support the Alert Event function for VigorAP 903 (with firmware 1.4.7 and above) only.