

Release Note for Vigor1000 Series

Firmware Version: 1.5.4.2

Release Date: December 04, 2014

Applied Models:

Vigor1000, Vigoe1000n, Vigor1000Vn

New Features

- None.

Improvement

- Corrected: Broadsoft call control didn't work.
- Corrected: A problem of one way audio occurred when an account registered via LAN/VPN.
- Corrected: SMS couldn't be sent via "bulksms.de".
- Improved: Support UBDDNS.
- Improved: SSL3 now disabled in favour of TLS by default for SSL tunnels and web management.

Known Issue

- None

Notes

Modifications

- None