

## Release Note for Vigor122 Series

Firmware Version:	3.2.10.1
Release Type:	<b>Critical</b> - Upgrade recommended immediately
Release Date:	December 21, 2016
Applied Models:	Vigor122 Series

- File and Modem Code

(1)For Annex A Model,

- "v122\_a\_3\_2\_10\_1" is used for modem code 321311. (Standard)
- "v122\_a1\_3\_2\_10\_1" is used for modem code 310801.
- "v122\_a2\_3\_2\_10\_1" is used for modem code 310811.
- "v122\_a3\_3\_2\_10\_1" is used for modem code 3211201
- "v122\_a4\_3\_2\_10\_1" is used for modem code 332201.
- "v122\_a5\_3\_2\_10\_1" is used for modem code 343601.
- "v122\_a6\_3\_2\_10\_1" is used for modem code 343701 (recommended for Italy).
- "v122\_a7\_3\_2\_10\_1" is used for modem code 3431301.
- "v122\_a8\_3\_2\_10\_1" is used for modem code 344001.
- "v122\_a9\_3\_2\_10\_1" is used for modem code 344101.
- "v122\_a10\_3\_2\_10\_1" is used for modem code 3471101.

(2)For Annex B Model,

- "v122\_b\_3\_2\_10\_1" is used for modem code 311112. (Standard)
- "v122\_b1\_3\_2\_10\_1" is used for modem code 3101212.
- "v122\_b2\_3\_2\_10\_1" is used for modem code 3101332.
- "v122\_b3\_3\_2\_10\_1" is used for modem code 311102.
- "v122\_b4\_3\_2\_10\_1" is used for modem code 346302.

## New Features

- None.

## Improvement

- Improved: Security improvements including one or more considered critical.

## Known Issue

- None