

## **Release Note for Vigor130 Series**

**Firmware Version: 3.7.6.1**

**Release Date: November 18, 2014**

**Applied Models:**

**Vigor130**

---

- **File and Modem Code**

(1)For Annex A Model,

- VDSL 548006 & ADSL 544401 (Standard)
- VDSL 547916 & ADSL 544411 will be used for Modem 1.
- VDSL 550e06 & ADSL 551001 will be used for Modem 2.
- VDSL 551506 & ADSL 551501 will be used for Modem 3.
- VDSL 567517 & ADSL 562301 will be used for Modem 4 (G.Vector).
- VDSL 571a17 & ADSL 570111 will be used for Modem 5 (G.Vector) recommended for Netherland ISP - KPN.
- VDSL 572d07 & ADSL 570e01 will be used for Modem 6 (G.Vector) recommended for Netherland ISP - KPN.
- VDSL 567517 & ADSL 562301 will be used for Modem 7(G.Vector) recommended for Germany DT.

(2)For Annex B Model,

- VDSL 548006 & ADSL 544512 (Standard)
- VDSL 542016 & ADSL 535112 will be used for Modem 1.
- VDSL 533d06 & ADSL 535902 will be used for Modem 2.
- VDSL 548006 & ADSL 544512 will be used for Modem 3.
- VDSL 565607 & ADSL 567002 will be used for Modem 4(G.Vector).
- VDSL 565607 & ADSL 567002 will be used for Modem 5, 6(G.Vector) recommended for Netherland ISP - KPN.
- VDSL 567617 & ADSL 567212 will be used for Modem 7(G.Vector) recommended for Germany DT.

## **New Features**

- Router management supports both SSLv3 / TLSv1.

- Modified UK Version according to SEG spec V3.

## **Improvement**

- Corrected: An ADSL PPPoE Passthrough issue for UK.
- Corrected: An issue with MPoA Bridge Mode + VLAN tag.
- Improved: Added the modem code 567517\_562301 & 567617\_567212 for DT, Germany.

## **Known Issue**

- None

## **Notes**

### ***Modifications***

- None