

Release Note for Vigor130 Series

Firmware Version: 3.7.6

Release Date: August 22, 2014

**Applied Models:
Vigor130**

- File and Modem Code

(1)For Annex A Model,

- VDSL 548006 & ADSL 544401 (Standard)
- VDSL 547916 & ADSL 544411 will be used for Modem 1.
- VDSL 550e06 & ADSL 551001 will be used for Modem 2.
- VDSL 551506 & ADSL 551501 will be used for Modem 3.
- VDSL 567517 & ADSL 562301 will be used for Modem 4 (G.Vector).
- VDSL 571a17 & ADSL 570111 will be used for Modem 5 (G.Vector) recommended for Netherland ISP - KPN.
- VDSL 572d07 & ADSL 570e01 will be used for Modem 6 (G.Vector) recommended for Netherland ISP - KPN.

(2)For Annex B Model,

- VDSL 548006 & ADSL 544512 (Standard)
- VDSL 542016 & ADSL 535112 will be used for Modem 1.
- VDSL 533d06 & ADSL 535902 will be used for Modem 2.
- VDSL 548006 & ADSL 544512 will be used for Modem 3.
- VDSL 565606 & ADSL 567002 will be used for Modem 4, 5, 6 (G.Vector) recommended for Netherland ISP - KPN.

New Features

- Add a new WUI named "Diagnostics >> DSL Status".
- UK Version. If the country code of your router is UK, there'll be a special customization.

Improvement

- Corrected: A PPPoE Passthrough / MPoA Bridge issue.

- Corrected: A PPP issue where PPP packets were sent even without username/password.
- Corrected: A PPP memory leakage issue.

Known Issue

- None

Notes

Modifications

- None