

Release Note for Vigor167

Firmware Version:	5.2.7
Release Type:	Regular – Upgrade recommended when convenient, as it includes general improvements and optimizations
Applied Models:	Vigor167

New Features

- None.

Improvement

- Corrected: An issue where the router returned incorrect data in its SNMP responses.
- Corrected: An issue where the configuration changed from ACS3 could not be applied to the Vigor167 in Router mode.

Known Issue

- To enhance security, firmware version 5.2.3 and the later version modified some system default values and implemented RE pattern checks and command injection checks on system parameters, fields, and values. These changes may cause configuration incompatibilities. Customers attempting to upgrade to the new firmware version may encounter issues such as the firmware version not changing after the upgrade or being unable to import previously backed-up configuration files. In such cases, we recommend that customers reset to factory default settings and reconfigure to resolve the issue.

File and Modem Code

- "Vigor167_v5.2.7.zip" provides modem code 5.12.31.0, and 5.12.18.17.