

## Release Note for Vigor2110 Series

**Firmware Version: 3.3.5.1**  
**Built Date: August, 4, 2010**  
**Applied Models:**  
**Vigor2110, Vigor2110n, Vigor2110Vn**

---

Please ensure you download and use the latest router tools when upgrading the firmware.

### New Features

- None

### Improvement

- Corrected: The Service Activation wizard is hidden for UK.
- Corrected: SSH remote management doesn't work when DMZ is open to a host.
- Corrected: The router does not accept the invite packet if the packet size is more than 2124 bytes.
- Corrected: Reboot problem occurs while T.38 is enabled and Fax is running.

### Related Information

- Get the document, please visit <http://www.draytek.com/user/PdInfoDetail.php?Id=85>
- Get the new firmware, please visit <http://www.draytek.com/user/SupportDownloads.php>
- Get the customer service support, please visit <http://www.draytek.com.tw/user/ContactHeadquarters.php>
- Get the regulatory compliance information <http://www.draytek.com.tw/user/AboutRegulatory.php>
- Get information for global partners <http://www.draytek.com.tw/user/Globalpartners.php>

## **Known Issue**

- None

## **Notes**

### ***Modifications***

- None