

## Release Note for Vigor2132 Series

Firmware Version:	3.8.0.3
Release Type:	Normal
Applied Models:	Vigor2132FVn, Vigor2132Vac

### New Features

- None.

### Improvement

- Improved: Modifications on DrayOS to meet the GDPR.
- Improved: Use a unified format for the Active Status.
- Improved: Use a unified format for enabling/disabling profile configuration.
- Improved: Enhanced the security on the web server.
- Improved: Update TR-069 parameters to be compatible with VigorACS2.
- Improved: Add an option for enabling/disabling TR-069 Server on System Maintenance>>Management.
- Improved: Modify the WAN physical type parameters for choosing on VigorACS server.
- Corrected: Unable to save the configuration after clicking OK on Applications >>Dynamic DNS Setup >>Dynamic DNS Account Setup.
- Corrected: Port redirection did not work after pressing OK on NAT>>Port Redirection.
- Corrected: Unable to synchronize the Physical Type (Ethernet) setting configured in WAN>>General Setup with the setting on VigorACS server.
- Corrected: Abnormal field display on VPN and Remote Access>>LAN to LAN.
- Corrected: Unable to access router's WUI due to LAN1 error after clicking OK on System Maintenance >> Management.
- Corrected: After unchecking the box of a static route on Routing>>Static Route, the disabled static route was still found on Diagnostics>>View Routing Table.
- Corrected: Unable to receive correct parameters for Primary DNS Server and Secondary DNS Server from VigorACS.
- Corrected: WAN type displayed on WAN>>Multi-WAN was not consistent with the physical type on WAN>>General Setup.

## Known Issue

- None.

## Notes

- Please use the latest boot-loader, or need to upgrade 3752\_B1 (ask your dealer) first, otherwise, it will encounter firmware upload issue.