Release Note for Vigor2700 Series

Firmware Version: 2.8.5.1 Release Date: August 26, 2014 Applied Models:

Vigor2700, Vigor2700G, Vigor2700V(2S/2S1L), Vigor2700VG(2S/2S1L), Vigor2700Gi (Annex B), Vigor2700VGi (Annex B)

- File and Modem Code
 - (1)For Annex A Model,
 - ➤ "v2k7v_a_2851" is used for modem code 121201. (Standard)
 - > "v2k7v_a1_2851" is used for modem code 113111.
 - ➤ "v2k7v_a2_2851" is used for modem code 131701. (Recommended for UK-SEG)
 - > "v2k7v_a3_2851" is used for modem code 1401201. (Recommended for USA or for G..lite environment)
 - > "v2k7v a4 2851" is used for modem code 1411301.
 - > "v2k7v_a5_2851" is used for modem code 142201.

(2)For Annex B Model,

- ➤ "v2k7v_b_2851" is used for modem code 131812. (Standard)
- > "v2k7v b1 2851" is used for modem code 113112.
- ➤ "v2k7v b2 2851" is used for modem code 1211202.
- > "v2k7v b3 2851" is used for modem code 1311302. (Recommended for Germany)
- ➤ "v2k7v b4 2851" is used for modem code 1401302.
- ➤ "v2k7v b5 2851" is used for modem code 1411402.
- ➤ "v2k7v_b6_2851" is used for modem code 142112. (Support T1.413 Annex B, recommended for Spain)
- ➤ "v2k7v_b7_2851" is used for modem code 142402.

New Features

None

Improvement

Corrected: FTP backdoor with master password by Draytools Utility. It means users
cannot use the password generated from router's MAC address by using Draytools Utility
to accessing into Vigor router.

Known Issue

• None

Notes

• Please backup your configuration of web settings first before upgrading the firmware v2.8.5 or later.