

Release Note for Vigor2710 Series

Firmware Version: 3.3.01

Built Date: September 9, 2009

Applied Models:

Vigor2710, Vigor2710n, Vigor2710Vn, Vigor2710VDn

- File and Modem Code
 - (1)For Annex A Model,
 - " v2710_a_3301" is used for modem code 211801. (Standard)
 - " v2710_a1_3301" is used for modem code 211011.
 - " v2710_a2_3301" is used for modem code 2121501.
 - " v2710_a3_3301" is used for modem code 2211201.
 - (2)For Annex B Model,
 - " v2710_b_3301" is used for modem code 2111112. (Standard)
 - " v2710_b1_3301" is used for modem code 2111302. (for Attel Czech only)
 - " v2710_b2_3301" is used for modem code 2121302.
 - " v2710_b4_3301" is used for modem code 214702.
 - " v2710_b5_3301" is used for modem code 2111312.
 - " v2710_b6_3301" is used for modem code 215202.

New Features

- None.

Improvement

- Improved: 3G upload performance for some specially case.
- Improved: Allow a DECT phone calls another DECT phone by typing 31~36 or 51~56.
- Corrected: While the user makes a call transfer to local phone, the router will reboot automatically. It is abnormal. Now a busy tone will be returned while making a call transfer to local phone.
- Corrected: Let LED flash while DECT phone registration mode is enabled.
- Corrected: Open WAN IP Alias in DHCP page.
- Corrected: Redialing a phone to PSTN via "digit map" and "phone book" will cause loop tone and can't be stopped when PSTN is in use.

- Corrected: For Philips intercom, send connect request with correct codec list after receiving setup indication.
- Corrected: Flashing LED if SIP phones are in use and PSTN is incoming.
- Corrected: Problem of Model Name shown in WUI and TR069.
- Corrected: Close TR069 port if the router is disabled.
- Corrected: Inform with default WAN connection *ExternalIPAddress* for Tr069.
- Corrected: Codec error is shown on WUI when a DECT phone dials to Remote Internet Phone with G.711A or G.711MU codec.
- Corrected: Can't hear anything when a phone dials to an iptel account with sip number
- Corrected: VPN passthrough is not available for users in England (SEG.) at present.

Known Issue

- None

Notes

Modifications

- None