

## Release Note for Vigor2710 Series

Firmware Version:	3.6.8.6
Release Type:	<b>Critical</b> - Upgrade recommended immediately
Release Date:	December 21, 2016
Applied Models:	Vigor2710, Vigor2710n, Vigor2710Vn, Vigor2710VDn

### New Features

- None.

### Improvement

- Improved: Security improvements including one or more considered critical.

### Known Issue

- None

### File and Modem Code

(1)For Annex A Model,

- " v2710\_a\_3686" is used for modem code 211011. (Standard)
- " v2710\_a1\_3686" is used for modem code 211801.
- " v2710\_a2\_3686" is used for modem code 2121501.
- " v2710\_a3\_3686" is used for modem code 2211201.
- " v2710\_a4\_3686" is used for modem code 232201. (Recommended for UK – SEG)
- " v2710\_a5\_3686" is used for modem code 243601.
- " v2710\_a6\_3686" is used for modem code 243701.
- " v2710\_a8\_3686" is used for modem code 244001.
- " v2710\_a7\_3686" is used for modem code 2431301.
- " v2710\_a9\_3686" is used for modem code 2471201.

(2)For Annex B Model,

- " v2710\_b\_3686" is used for modem code 2111112. (Standard)
- " v2710\_b1\_3686" is used for modem code 2111302. (Recommended for Attel Czech only)
- " v2710\_b2\_3686" is used for modem code 2121302 (recommended for Slovskia only).

- " v2710\_b4\_3686" is used for modem code 214702.
- " v2710\_b5\_3686" is used for modem code 2111312.
- " v2710\_b6\_3686" is used for modem code 215202.
- " v2710\_b7\_3686" is used for modem code 246302.