

## Release Note for Vigor2710 Series

Firmware Version:	3.7.2
Release Type:	Normal
Applied Models:	Vigor2710, Vigor2710n, Vigor2710Vn, Vigor2710VDn

### New Features

- None.

### Improvement

- This firmware includes improvements to harden the web interface against attacks. We have become aware of specific attacks against router, including DrayTek, models where hackers have altered specific settings relating to your DNS servers and DHCP settings. You should urgently check those settings on your router. If they appear to have been tampered with, correct them and change your admin password and check for any other config anomalies. Restore a config backup if you have one (from prior to the attack). We continue to investigate this issue but the first priority was to issue updated firmware.

### Known Issue

- None

### File and Modem Code

(1)For Annex A Model,

- "v2710\_a\_372" is used for modem code 211011. (Standard)
- "v2710\_a1\_372" is used for modem code 211801.
- "v2710\_a2\_372" is used for modem code 2121501.
- "v2710\_a3\_372" is used for modem code 2211201.
- "v2710\_a4\_372" is used for modem code 232201. (Recommended for UK – SEG)
- "v2710\_a5\_372" is used for modem code 243601.
- "v2710\_a6\_372" is used for modem code 243701.
- "v2710\_a8\_372" is used for modem code 244001.
- "v2710\_a7\_372" is used for modem code 2431301.
- "v2710\_a9\_372" is used for modem code 2471201.
- "v2710\_a10\_372" is used for modem code 252901.

(2)For Annex B Model,

- "v2710\_b\_372" is used for modem code 2111112. (Standard)
- "v2710\_b1\_372" is used for modem code 2111302. (Recommended for Attel Czech only)
- "v2710\_b2\_372" is used for modem code 2121302 (recommended for Slovskia only).
- "v2710\_b4\_372" is used for modem code 214702.
- "v2710\_b5\_372" is used for modem code 2111312.
- "v2710\_b6\_372" is used for modem code 215202.
- "v2710\_b7\_372" is used for modem code 246302.