

Release Note for Vigor2710 Series

Firmware Version:	3.7.3
Release Type:	Normal
Applied Models:	Vigor2710, Vigor2710n, Vigor2710Vn, Vigor2710VDn

This is a critical update - You should upgrade such Vigor router immediately with firmware containing these improvements.

New Features

- None.

Improvement

- Enhanced the security on the web server.

Known Issue

- None

File and Modem Code

(1)For Annex A Model,

- "v2710_a_373" is used for modem code 211011. (Standard)
- "v2710_a1_373" is used for modem code 211801.
- "v2710_a2_373" is used for modem code 2121501.
- "v2710_a3_373" is used for modem code 2211201.
- "v2710_a4_373" is used for modem code 232201. (Recommended for UK – SEG)
- "v2710_a5_373" is used for modem code 243601.
- "v2710_a6_373" is used for modem code 243701.
- "v2710_a8_373" is used for modem code 244001.
- "v2710_a7_373" is used for modem code 2431301.
- "v2710_a9_373" is used for modem code 2471201.
- "v2710_a10_373" is used for modem code 252901.

(2)For Annex B Model,

- "v2710_b_373" is used for modem code 2111112. (Standard)
- "v2710_b1_373" is used for modem code 2111302. (Recommended for Attel Czech)

only)

- "v2710_b2_373" is used for modem code 2121302 (recommended for Slovakia only).
- "v2710_b4_373" is used for modem code 214702.
- "v2710_b5_373" is used for modem code 2111312.
- "v2710_b6_373" is used for modem code 215202.
- "v2710_b7_373" is used for modem code 246302.