

Release Note for Vigor2830n V2

Firmware Version:	3.8.8.2
Release Type:	Critical
Applied Models:	Vigor2830n V2

Vigor2830n V2 is an ADSL2+ router. It integrates IP layer QoS, NAT session/bandwidth management to help users control works well with large bandwidth. The gigabit WAN2 and 4-port gigabit LAN switch facilitates unified communication applications in business CO/remote site to handle large data from subscribed fatter pipe.

This is a critical update - You should upgrade such Vigor router immediately with firmware containing these improvements.

New Features

- None.

Improvement

- This firmware includes improvements to harden the web interface against attacks. We have become aware of specific attacks against router, including DrayTek models where hackers have altered specific settings relating to your DNS servers and DHCP settings. You should urgently check those settings on your router. If they appear to have been tampered with, correct them and change your admin password and for any other config anomalies. Restore a config backup if you have one (from prior to the attack). We continue to investigate this issue but the first priority was to issue updated firmware.

File and Modem Code

Available modem codes for Annex A/Annex B are displayed as follows:

For Annex A Model,

- "Vigor2830n-v2_v3.8.8.2-00_en.zip" is used for modem code 548006_544401 & 560816_552011
- "Vigor2830n-v2_v3.8.8.2-01_en.zip" is used for modem code 567517_562301 & 566f07_562701
- "Vigor2830n-v2_v3.8.8.2-02_en.zip" is used for modem code 574307_571801 & 573807_571701

For Annex B Model,

- "Vigor2830n-v2_v3.8.8.2-00_en.zip" is used for modem code 548006_544512 & 551716_553312
- "Vigor2830n-v2_v3.8.8.2-01_en.zip" is used for modem code 565607_567002 & 565606_567002
- "Vigor2830n-v2_v3.8.8.2-02_en.zip" is used for modem code 573307_571c02 & 565607_567002

Known Issue

- None