

Release Note for Vigor2832 Series

Firmware Version:	3.9.5
Release Type:	Normal
Applied Models:	Vigor2832, Vigor2832n

Vigor2832 series is an ADSL2/2+ modem router with an alternative Gigabit Ethernet WAN port for load-balancing or failover. It has 4 Gigabit Ethernet LAN ports and 2 USB ports which can be used for 3G/4G WAN, temperature sensor, or NAS application. Models with built-in 802.11n Wi-Fi are available.

File and Modem Code

"Vigor2832_v3.9.5-00_en.zip" provides Annex A modem code 06-06-01-07-00-01, and Annex B modem code 06-06-00-02-01-02.

New Features

- None.

Improvement

- Corrected: An issue of failure to do network connection with WAN3.
- Corrected: An issue of default route missed after disabling a static route.
- Corrected: Issues related to firmware upgrade via VigorACS and router's WUI.
- Corrected: An issue of failure to set the WAN budget configuration via VigorACS server.
- Corrected: An issue of failure to read/write files greater than 2G via SMB server on WIN10.
- Corrected: An issue of self-signed certificate regeneration automatically of Vigor router before expiration.

Known Issue

- None.