Release Note for Vigor2850 Series

Firmware Version: 3.3.6.1 Built Date: September, 15, 2011 Applied Models: Vigor2850/Vigor2850n/Vigor2850Vn

Vigor2850 series is a **VDSL2** router with **multi-subnet** for secure and efficient workgroup management. It integrates IP layer QoS, NAT session/bandwidth management to help users control works well with large bandwidth.

• File and Modem Code

(1)For Annex A Model,

- "v2850_a_v03361" is used for modem code 211801(Standard).
- ➤ "v2850_a2_v03361" is used for modem code 2121501.
- > "v2850_a3_v03361" is used for modem code 2211201.
- "v2850_a4_v03361" is used for modem code 232201 (recommended for UK-SEG only)
- > "v2850_a5_3361" is used for modem code 243601.
- > "v2850_a6_3361" is used for modem code 243701.
- ▶ "v2850_a7_3361" is used for modem code 2431301.
- > "v2850_a8_3361" is used for modem code 244001.
- > "v2850_a9_3361" is used for modem code 2471201.
- (2)For Annex B Model,
 - ▶ "v2850_b_3361" is used for modem code 2111112. (Standard)
 - "v2850_b1_3361" is used for modem code 2111302 (recommended for Czech only)
 - "v2850_b2_3361" is used for modem code 2121302.(recommended for Slovakia only)
 - ➤ "v2850_b4_3361" is used for modem code 214702.
 - ➤ "v2850_b5_3361" is used for modem code 2111312.
 - ➤ "v2850_b6_3361" is used for modem code 215202.
 - ▶ "v2850_b7_3361" is used for modem code 246302.

New Features

• Support Dual-WAN.

Improvement

• None.

Known Issue

• None

Notes

Modifications

• None