

## Release Note for Vigor2862 Series

Firmware Version:	3.9.1.3
Release Type:	Normal
Applied Models:	Vigor2862 / Vigor2862n / Vigor2862ac / Vigor2862Vac / Vigor2862L / Vigor2862Ln / Vigor2862Lac

Vigor2862 series is a VDSL2 router with multi-subnet for secure and efficient workgroup management. It integrates IP layer QoS, NAT session/bandwidth management to help users control works well with large bandwidth. Besides, “n” and “ac” series have built-in Wireless LAN for wireless connection.

### New Features

- None.

### Improvement

- Improved: Refine the local certificate to meet the new security policy of Apple iOS 13 for SSL VPN connection.

### File and Modem Code

For DSL models, there will be three folders: STD, MDM1 and MDM2. The files in MDM1 and MDM2 named folder include different modem codes. If you're using a VDSL line, MDM1 and MDM2 named firmware may bring out better performance. Available modem codes for Annex A/Annex B are displayed as follows:

#### For Annex A Model,

- "Vigor2862\_v3.9.1.3\_STD\_en.zip" is used for modem code 776d07\_772801\*, 774307\_771801\*
- "Vigor2862\_v3.9.1.3\_MDM1\_en.zip" is used for modem code 779517\_773F01\*, 77B507\_775401\* (recommended for Australia)
- "Vigor2862\_v3.9.1.3\_MDM2\_en.zip" is used for modem code 77B506\_775401, 778C06\_773F01

\* stands for vectoring modem code

#### For Annex B Model,

- "Vigor2862\_v3.9.1.3\_STD\_en.zip" is used for modem code 773306\_771502, 773307\_771C02\*

- "Vigor2862\_v3.9.1.3\_MDM1\_en.zip" is used for modem code 779B06\_774F02, 779B07\_774C12\*
  - "Vigor2862\_v3.9.1.3\_MDM2\_en.zip" is used for modem code 779906\_774402, 779B06\_774C02
- \* stands for vectoring modem code

## Known Issue

- None.