

Release Note for Vigor2862B Series

Firmware Version:	3.9.1.3
Release Type:	Normal
Applied Models:	Vigor2862B / Vigor2862Bn

Vigor2862B/Bn is a VDSL2 router with multi-subnet for secure and efficient workgroup management. It integrates IP layer QoS, NAT session/bandwidth management to help users control works well with large bandwidth. In which, Vigor2862B series can support VDSL2 Bonding. By connected to a pair of bonded VDSL line, it can get a doubled transmission rate, or get the same rate but over a longer distance. Besides, Vigor2862Bn has built-in Wireless LAN for wireless connection.

New Features

- None.

Improvement

- Improved: Refine the local certificate to meet the new security policy of Apple iOS 13 for SSL VPN connection.

File and Modem Code

For DSL models, there will be three folders: Bonding, Bonding_MDM1 and Bonding_MDM2. The files in Bonding_MDM1 named folder include different modem codes. If you're using a VDSL line, Bonding_MDM1 named firmware may bring out better performance. Available modem codes for Annex A/Annex B are displayed as follows:

For Annex A Model,

- "Vigor2862_v3.9.1.3_Bonding_en.zip" is used for modem code 776d07_772801*, 774307_771801*
 - "Vigor2862_v3.9.1.3_Bonding_MDM1_en.zip" is used for modem code 779517_773F01*, 77B507_775401*
 - "Vigor2862_v3.9.1.3_Bonding_MDM2_en.zip" is used for modem code 77B506_775401, 778C06_773F01
- * stands for vectoring modem code

For Annex B Model,

- "Vigor2862_v3.9.1.3_Bonding_en.zip" is used for modem code 773306_771502, 773307_771C02*
 - "Vigor2862_v3.9.1.3_Bonding_MDM1_en.zip" is used for modem code 779B06_774F02, 779B07_774C12*
 - "Vigor2862_v3.9.1.3_Bonding_MDM2_en.zip" is used for modem code 779906_774402, 779B06_774C02
- * stands for vectoring modem code

Known Issue

- None.