

## Release Note for Vigor2866 Series

Firmware Version:	4.4.6.2
Release Type:	Regular – Upgrade recommended when convenient, as it includes general improvements and optimizations
Applied Models:	Vigor2866 / Vigor2866ac / Vigor2866L / Vigor2866Lac / Vigor2866ax / Vigor2866Vac

Vigor2866 Series is a G.fast Security Firewall router integrating a DSL modem which is compatible with variants of DSL protocols, including G.fast, VDSL2 profile 35b Super Vectoring, and ADSL2+.

### New Features

- None.

### Improvement

- Corrected: An issue with a router reboot due to the Web GUI.
- Corrected: An issue with a router reboot when receiving a suspicious TCP packet.
- Corrected: An issue where the router rebooted when DNS Filter, URL Filter, Web Content Filter, or Application Enforcement was enabled and TLS 1.3 hybridized Kyber was used.
- Corrected: An issue where the router rebooted when both WCF and DNS Filters were enabled and the Internet connection was unstable or interrupted.

### Known Issue

- A firewall can restrict/drop unwanted inbound WAN traffic such as VPN requests. The router's firewall block rules can stop remote management and VPN access. It is recommended to review the firewall settings before upgrading.
- QoS does not work on G.fast line when the link rate exceeds 600 Mbps.
- For "ax" series model:  
The wireless clients might encounter unexpected trouble (e.g., unable to use the printer on LAN) while accessing into Internet if the hardware acceleration is enabled.  
To skip hardware acceleration for certain devices, the following telnet command can be used:  

```
ppa -E -e 1  
ppa -E -a AA:BB:CC:XX:XX:XX nat|bridge|ipsec
```
- Vigor2866 may have synchronization or performance issues when connecting to the DSL line with a lower SNR value (<6).

## File and Modem Code

- "Vigor2866\_v4.4.6.2\_STD.zip" provides Annex A modem code 123230\_02 and 123210\_30.
- "Vigor2866\_v4.4.6.2\_MDM1.zip" provides Annex A modem code 126110\_12 and 126010\_15.
- "Vigor2866\_v4.4.6.2\_MDM2.zip" provides Annex A modem code 127210\_04 and 127110\_01. Recommended for Australian users
- "Vigor2866\_v4.4.6.2\_MDM3.zip" provides Annex J modem code 127210\_04 and 127110\_01. Recommended for Germany, Austrian and Swiss users
- "Vigor2866\_v4.4.6.2\_MDM4.zip" provides Annex A modem code 128210\_02 and 127210\_04. Recommended for Australian users
- "Vigor2866\_v4.4.6.2\_MDM5.zip" provides Annex J modem code 128210\_02 and 127210\_04. Recommended for German users.
- "Vigor2866\_v4.4.6.2\_MDM6.zip" provides Annex A modem code 129120\_05, 128210\_02. (Recommended when meeting VDSL sync issue).
- "Vigor2866\_v4.4.6.2\_MDM7.zip" provides Annex J modem code 129120\_05, 128210\_02.

VDSL2 Profile 30a is supported by modem code 129120\_05(MDM6/MDM7).

## Note

- IPsec HMAC (MD5) is no longer supported.