Release Note for Vigor2912 Series

Firmware Version: 3.7.5.1
Release Date: June 10, 2014
Applied Models:
Vigor2912/Vigor2912n/Vigor2912F/Vigor2912Fn

Vigor2912 series is a broadband router which integrates IP layer QoS, NAT session/bandwidth management to help users control works well with large bandwidth.

New Features

• Add Fiber function (100Mbps).

Improvement

- Corrected: A Multi-VLAN WAN can not bridge packets to LAN ports when it is untagged.
- Corrected: The DHCP relay of a tagged LAN subnet can not work.
- Corrected: AirPrint can not work after a period of time.
- Corrected: Wireless Access Control does not work after reboot.
- Corrected: Mac OS computers on Wireless LAN lost traffic after a period of time.
- Corrected: Firewall does not block IPv6 routing packets from WAN.

Known Issue

• None.

Notes

Modifications

None