

## Release Note for Vigor2912 Series

**Firmware Version: 3.8.1.2**

**Release Date: May 16, 2016**

**Applied Models:**

**Vigor2912/Vigor2912n/Vigor2912F/Vigor2912Fn**

---

Vigor2912 series is a broadband router which integrates IP layer QoS, NAT session/bandwidth management to help users control works well with large bandwidth.

### New Features

- None.

### Improvement

- Corrected: Router reboots if country code is 0x2F(Iraq) or 0x3a(Sri Lanka).

### Known Issue

- If TR-069 settings have been set once, the router continuously crashes after downgrading to v3.7.8 firmware.  
Workaround: Add telnet command "sys tr069 clear" to clear TR-069 config in flash.  
Users can use this command before downgrade to avoid this problem. (But all TR-069 settings will be cleared.)

### Notes

#### *Modifications*

- None