

Release Note for Vigor2920 Series

Firmware Version: 3.3.2.3
Built Date: March, 04, 2009
Applied Models:
Vigor2920/Vigor2920n

Vigor2920 series, a firewall broadband router with dual-WAN interface, can connect to xDSL/cable/VDSL2/Ethernet. The gigabit 2nd WAN and 4-port gigabit LAN switch facilitates unified communication applications in business CO/remote site to handle large data from subscribed fatter pipe. The state-of-art routing feature, VPN security, and Dual-WAN provide integrated benefits for professional users and small offices.

New Features

- None.

Improvement

- Corrected: LAN may not work after switch initialization completed.
- Corrected: show session problem on **Diagnostics >> LAN Security Monitor** page. (In previous version, it was **Data Flow Monitor**.)
- Corrected: The router reboots while carrying out two consecutive Call Transfers.
- Improved: Modify the value of DDNS Auto-Update interval from 1440 to 14400.
- Improved: Find out a buffer leakage problem.
- Improved: In IE6, the web page of the router cannot display detailed information about firmware upgrade which is performed by VigorACS SI.

Known Issue

- None

Notes

Modifications

- None