Release Note for Vigor2920 Series

Firmware Version: 3.3.3.1 Built Date: July, 05, 2010 Applied Models: Vigor2920/Vigor2920n/2920Vn

Vigor2920 series, a firewall broadband router with dual-WAN interface, can connect to xDSL/cable/VDSL2/Ethernet. The gigabit 2nd WAN and 4-port gigabit LAN switch facilitates unified communication applications in business CO/remote site to handle large data from subscribed fatter pipe. The state-of-art routing feature, VPN security, and Dual-WAN provide integrated benefits for professional users and small offices.

New Features

Be able to change TR-069 CPE Client username and password.

Improvement

- Corrected: WUI display errors for UK.
- Corrected: Unable to block Google Document Upload when GDoc Uploader in Object
 Settings>>Misc Object is checked and enabled.
- Corrected: Might get reboot problem while doing Call Waiting service.
- Corrected: Might get reboot problem after run "ip igmp_proxy status" and "ip igmp_snoop status" commands.
- Corrected: Save problem occurs for Interval Time of Periodic Inform Settings in System Maintenance>>TR-069.
- Corrected: The TR-069 parameter (LANDevice.1.WLANConfiguration.1.Channel) shows wrong value.
- Corrected: PPP status will cause router redialing L2TP WAN.
- Corrected: When the VPN server is behind Vigor NAT and uses DMZ (by True IP) to get IP address, Vigor NAT will block both VPN client's and VPN server's GRE request.
- Improved: Bandwidth limit does not work correctly.
- Improved: Update routing policy for China CNC & CNT.

• Improved: Cannot create VPN IPSec tunnel with PIX Firewall when the authentication is done by using X509.

Related Information

Get the document, please visit http://www.draytek.com.tw/user/PdInfoDetail.php ?Id=114#PdInfo Get the new firmware, please visit www.draytek.com.tw/user/SupportDownloads.php ?Type=Firmware Get the customer service support, http://www.draytek.com.tw/user/ContactHeadquar please visit ters.php Get the regulatory compliance http://www.draytek.com.tw/user/AboutRegulatory. information php Get information for global partners http://www.draytek.com.tw/user/Globalpartners.p <u>hp</u>

Known Issue

None

Notes

Modifications

None