

Release Note for Vigor2926 Series

Firmware Version:	3.8.9.1
Release Type:	Normal
Applied Models:	Vigor2926, Vigor2926n, Vigor2926ac, Vigor2926L, Vigor2926Vac, Vigor2926Ln, Vigor2926Lac

Vigor2926 series is a broadband router which integrates IP layer QoS, NAT session/bandwidth management to help users control works well with large bandwidth. The state-of-art routing feature, VPN security, and Dual-WAN provide integrated benefits for professional users and small offices.

New Features

- WAN2 can be configured as LAN port 5.

Improvement

- Corrected: The settings in APP Enforcement Profiles were messed up, after upgrading the firmware to Version 3.8.9.
Suggestion: Choose one of the following methods to upgrade the router firmware.
 - Upgrade the firmware from the old version to new version (V3.8.9.1) directly.
 - Upgrade the firmware to V3.8.9 by using “x.all”. Do not modify the APP profile configuration and then upgrade the firmware to 3.8.9.1.
- Corrected: When enabling Data Flow Monitor, Bandwidth Limit and Dynamic DNS Setup, the system would reboot after logging into web user interface.
- Corrected: Vigor router reboot randomly due to incompliant with TR-069 server.

Known Issue

- None.