

Release Note for Vigor2952 Series

Firmware Version:	3.9.1.1
Release Type:	Normal
Applied Models:	Vigor2952, Vigor2952P, Vigor2952n, Vigor2952Pn

Vigor2952 is a broadband router with dual-WAN interface. It provides policy-based load-balance, fail-over and BoD (Bandwidth on Demand), also it integrates IP layer QoS, NAT session/bandwidth management to help users control works well with large bandwidth.

New Features

- None.

Improvement

- Corrected: Policy routes with different NATed VPN interfaces did not work when there were more than one NATed VPN tunnels established.
- Corrected: Vigor router rebooted constantly when HTTPs was selected for TR-069.
- Corrected: Vigor router rebooted as soon as the SSH session from a LAN PC times out.
- Corrected: Unable to use port 1194 even OpenVPN service was disabled.
- Corrected: IPsec Xauth VPN connection from a specific mobile phone caused router reboot.

Known Issue

- None.

Note

- Use MFUU Tools or Console TFTP to upgrade firmware version if failing to use web user interface for firmware upgrade.