

## Release Note for Vigor2952 Series

Firmware Version:	3.9.8.7
Release Type:	Important – Review release notes and upgrade if the changes affect your system stability, performance, or security
Applied Models:	Vigor2952, Vigor2952P, Vigor2952n, Vigor2952Pn

Vigor2952 is a broadband router with dual-WAN interface. It provides policy-based load-balance, fail-over and BoD (Bandwidth on Demand), also it integrates IP layer QoS, NAT session/bandwidth management to help users control works well with large bandwidth.

### New Features

- None.

### Improvement

- Corrected: An issue with a router reboot due to the Web GUI.
- Corrected: An issue with a router reboot when receiving a suspicious TCP packet.
- Corrected: An issue with failure of applying the access list through VigorACS server.
- Corrected: An issue with failure to retain the configuration when applying a new .def file from the VigorACS server.
- Corrected: An issue with failure to get the correct firmware by clicking the Download Directly button on System Maintenance>>Firmware Upgrade.
- Corrected: An issue where the router rebooted when DNS Filter, URL Filter, Web Content Filter, or Application Enforcement was enabled and TLS 1.3 hybridized Kyber was used.

### Known Issue

- None.