

Release Note for Vigor300B

Firmware Version: 1.1.0.2
Release Date: September 17, 2015
Applied Models: Vigor300B

Vigor300B, a firewall broadband router with multi-WAN interface, can connect to xDSL/cable/VDSL2/Ethernet FTTx. The multi-WAN and LAN switch facilitate unified communication applications in business CO/remote site to handle large data from subscribed fatter pipe. The state-of-art routing feature, and multi-WAN provide integrated benefits for professional users and small offices.

New Features

- None.

Improvement

- Fixed: "Fail to Ban" could not work for SSH login.
- Fixed: Port Redirection didn't work for specific configuration.
- Fixed: Syslog stopped writing to USB disk after reboot.
- Fixed: Unable to modify Telnet login Max-Failed Times in Fail to Ban.
- Fixed: Unable to display Netbios Name in ARP Cache Table.
- Fixed: Maximum session limits can be shown with 10000 only in online status web page.
- Improved: WAN failed over time.
- Improved: Support 4G Dongle Huawei E3372.
- Improved: Upgrade OpenSSL to 0.9.8zg for vulnerabilities.

Known Issue

- None

Notes

Modifications

- None