Release Note for Vigor300B

Firmware Version:	1.4.4
Release Type:	Normal
Applied Models:	Vigor300B

Vigor300B, a firewall broadband router with the multi-WAN interface, can connect to xDSL/cable/VDSL2/Ethernet FTTx. The multi-WAN and LAN switch facilitates unified communication applications in business CO/remote site to handle large data from the subscribed fatter pipe. The state-of-art routing feature and multi-WAN provide integrated benefits for professional users and small offices.

New Features

None.

Improvement

- Improved: Support Switch Management for VigorSwitch G1280.
- Improved: Unify the format of AP Management /Switch Management support list.
- Corrected: Failed to update DDNS.
- Corrected: High CPU usage when running PPPoE server for 100 clients.
- Corrected: For the web portal, the PC would be directed to a null web page after clicking the OK button in the Bulletin Board.
- Corrected: For the web portal, the logout function did not work with the Chrome Browser.
- Corrected: Vigor router did not offer IP for IKEv2 EAP user integrated with RADIUS and DHCP relay.
- Corrected: Did not list VigorAP903 on Central Management>>AP Management.
- Corrected: Unable to import IP bind MAC file if login language wasn't English.

Known Issue

None