

Release Note for Vigor3100

Firmware Version: V2.8.2.1

Date: November 27, 2008

Applied Models:

Vigor3100, Vigor3100G, Vigor3100V, Vigor3100i, Vigor3120

New Features

- Add telnet command "srv nat ipsecpass" for IPSec NAT passthrough.
- Add WAN interface in static route web page.
- Support PPPoA bridge function.
- Support Bandwidth Limit function for 2nd subnet.
- Support TFTP ALG.
- Support more 3.5G modems(C-Motech D-50, CDU-550, Sierra 875U, ASUS T500 and OVATION MC950D). The supported modems are listed on DrayTek web site.

Improvement

- Fix the problem that PPTP HOST-To-LAN can only set up 16 VPN connections.
- Update CPA URL.
- Improve DHCP function.
- Set the default WAN detection mode of MPoA as ARP detection.

Known Issue

- None

Notes

Modifications

- None

Bug Lists

- None