

# Release Note for VigorAP 710

**Firmware Version: 1.1.2**  
**Release Date: November 27, 2014**  
**Applied Models: VigorAP 710**

---

With this high cost-efficiency VigorAP 710, computers and wireless devices which are compatible with 802.11n can connect to existing wired Ethernet network via this VigorAP710, at higher speed. Easy install procedures allows any computer users to setup a network environment in very short time - within minutes, even inexperienced users.

## New Features

- None.

## Improvement

- Corrected: AirPrint could not work after a period of time.
- Corrected: Display error of SSID when Universal Repeater is specified as Operation Mode in quick Start Wizard.
- Improved: Stability of multi-user wireless connection.
- Improved: Replace the word of Router with AP in certain web page (e.g., **System Maintenance>>Reboot System**).
- Corrected: MAC information on Syslog was disappeared when a Wi-Fi client connected to VigorAP 710 by WPA2/PSK.
- Corrected: If VigorAP 710 was unplugged and then connected to Vigor router again, it could not be detected correctly through the function of **External Device** of Vigor router (e.g., Vigor2860).
- Improved: The DHCP mode could not show default gateway IP address.
- Corrected: 2.4Ghz LED wouldn't turn off when disabling 2.4GHz wireless LAN by schedule.
- Corrected: Problems with Universal Repeater mode occurred when wireless client connected using DHCP.
- Corrected: No IP lease received when using VLAN tag.
- Improved: Enhanced for SSLv3 Fallback protection.

## **Known Issue**

- None

## **Notes**

### ***Modifications***

- None