

Release Note for VigorAP 800

Firmware Version: 1.1.3
Release Date: January 15, 2014
Applied Models: VigorAP 800

"With this high cost-efficiency VigorAP 800, computers and wireless devices which are compatible with 802.11n can connect to the existing Ethernet network via this VigorAP800. 300Mbps wireless transmission rates is ideal for bandwidth-heavy tasks. Easy install procedures allow any computer users to setup a network environment in very short time - within minutes, even inexperienced users."

New Features

- None.

Improvement

- Improved: After pressing the WPS button over six seconds, the APM will be disabled. Current LAN IP and Mask will be regarded as default settings.
- Improved: A warning window will pop up when the characters typed for Administrator Password are over the limitation.
- Improved: HTMIX is fixed for WDS Phy Mode.
- Improved: Add a note for Access Control entries.
- Fixed: Can't enable WPA2/802.1x (Radius) mode for SSID3 and SSID4.
- Fixed: Traffic Graph displayed wrong graphic.
- Fixed: LAN IP is effective only restarting the VigorAP800 manually.
- Fixed: If the wireless function of VigorAP800 is disabled, it cannot be enabled by APM again.
- Fixed: Airprint can't work with VigorAP800.
- Fixed: VigorAP800 does not forward IGMP traffic correctly.
- Fixed: WLAN OFF Button on outer case can not turn off WLAN function.

Related Information

- Get the document, please visit <http://www.draytek.com/user/PdInfoDetail.php?Id=122>

- Get the new firmware, please visit
<http://www.draytek.com/user/SupportDownloads.php>
- Get the customer service support, please visit
<http://www.draytek.com/user/ContactHeadquarters.php>
- Get the regulatory compliance information
<http://www.draytek.com/user/AboutRegulatory.php>
- Get information for global partners
<http://www.draytek.com/user/Globalpartners.php>

Known Issue

- None

Notes

Modifications

- None