

## Release Note for VigorAP 802

Firmware Version:	1.3.4
Release Type:	Normal
Applied Models:	VigorAP 802

VigorAP 802, a 11ac dual-band wall plug AP, can be used to bridge any Ethernet device to a network. It is not necessary for you to spend time and money installing expensive Ethernet cable to share your Internet connection or HD / SD video stream at home. Just plug VigorAP 802 to the power outlet on the wall. You can get stable and fast speed for data transmission at any site in your house.

### New Features

- None.

### Improvement

- Improved: Improved the Web GUI security.
- Improved: Improve the SNMP mechanism to have more security.
- Improved: Add a new selection (FCC) for Regulation for VN (country code).
- Improved: Modify Draytek AP A-Band Channel List for Israel, UAE, SA, Australia and Thailand.
- Corrected: A wireless encryption configuration issue over APM.
- Corrected: An issue of display error for TX Link Speed for wireless station.
- Corrected: An issue of VigorAP (as a node in hop2) disabling to be online again after offline.
- Corrected: An issue that the DHCP server in AP would cause multiple firmware upgrades not working.
- Corrected: An issue that wireless 5G client failed to connect to AP, after editing AP's configuration via VigorACS.

### Known Issue

- None.

## Notes

- None.