

Release Note for VigorAP 810

Firmware Version: 1.1.3
Release Date: February 03, 2015
Applied Models: VigorAP 810

With this high cost-efficiency VigorAP 810, computers and wireless devices which are compatible with 802.11n can connect to existing wired Ethernet network via this VigorAP 810, at the speed of 300Mbps. Easy install procedures allows users to setup a network environment in very short time - within minutes, even inexperienced users. Just follow the instructions given in this user manual, you can complete the setup procedure and release the power of this access point all by yourself!

New Features

- None.

Improvement

- Improved: Modify default profile parameters for EN300328 certification
- Improved: Support related parameters of TR-111 for managed by VigorACS SI.
- Improved: Add a warning message when the typed SSID characters are invalid.
- Improved: Fix that only "Vigor" can be displayed for model name in VigorACS SI.
- Improved: Support to enable TCP cookies function to block SYN attack.
- Corrected: Fix the problems with Universal Repeater mode when wireless client connects using DHCP.
- Corrected: Fix the function failure of Wireless LAN Limit Client.
- Corrected: While choosing AP Bridge-Point to Point operation mode in **Quick Start Wizard**, no detected AP can be chosen from the pop-up window of AP Discovery.
- Corrected: Channel for wireless LAN(2.4G), configured by **Central AP Management >> WLAN Profile** from Vigor router, but non-existed in VigorAP would be shown on System Status.
- Corrected: Daylight Saving is incorrect for AU/NZ.
- Corrected: When VigorAP reboots, the system cannot auto update time from NTP.
- Corrected: Wireless LAN (2.4GHz) is still shown as enabled in **Wireless LAN >>General Setup** after scheduled Wi-Fi (2.4GHz) connection down.
- Corrected: Schedule can be enabled, but not disabled.

Known Issue

- None

Notes

Modifications

- None