

Release Note for VigorAccess IPDSLAM module

Firmware Version: 2.10.2.24.0

Date: Oct 21, 2009

**Applied Models:
VigorAccess IPDSLAM A48**

New Features

- None

Improvement

- Corrected: when over night test is done by IXIA via SFP port, data loss and CRC error will happen to G4 port.
- Corrected: multicast content on DSL IGMP status is cleared and causes break down of the clients while testing IPTV mode.
- Corrected: some problems of IP Configure in Web system.
- Corrected: error message of "\$IgmP_HandleQryGrpInStableState psGrpInfo->u32LastResponseTime=100" will be shown on DSL console while testing IPTV mode.
- Corrected: DHCP client cannot get dynamic IP address when DHCP option 82 is enabled.
- Corrected: a message of "IGMP_QUERY EXIT Without Free Frame" appears via console port while IPTV mode is tested and closed by the client.
- Corrected: spelling error of title in PVC MAC profile on WUI.
Modify the title for the Web System and Bridge on WUI.
- Modify the range of VCI with the values, 32~65535.

Known Issue

- None

Notes

- None