

Release Note for Vigor120 Series

Firmware Version: 3.2.8
Release Date: July 07, 2015
Applied Models:
Vigor120 (V2)

- File and Modem Code

(1)For Annex A Model,

- "v12x_a_v328" is used for modem code 321311. (Standard)
- "v12x_a1_v328" is used for modem code 310801.
- "v12x_a2_v328" is used for modem code 310811.
- "v12x_a3_v328" is used for modem code 3211201
- "v12x_a4_v328" is used for modem code 332201.
- "v12x_a5_v328" is used for modem code 343601.
- "v12x_a6_v328" is used for modem code 343701 (recommended for Italy).
- "v12x_a7_v328" is used for modem code 3431301.
- "v12x_a8_v328" is used for modem code 344001.
- "v12x_a9_v328" is used for modem code 344101.
- "v12x_a10_v328" is used for modem code 3471101.

(2)For Annex B Model,

- "v12x_b_v328" is used for modem code 311112. (Standard)
- "v12x_b1_v328" is used for modem code 3101212.
- "v12x_b2_v328" is used for modem code 3101332.
- "v12x_b3_v328" is used for modem code 311102.
- "v12x_b4_v328" is used for modem code 346302.

New Features

- Support "Auto Reboot Time Schedule".

Improvement

- None.

Known Issue

- None

Notes

Modifications

- None