

Release Note for Vigor130 Series

Firmware Version: 3.7.5.2
Release Date: June 25, 2014
Applied Models:
Vigor130

- File and Modem Code

(1)For Annex A Model,

- VDSL 548006 & ADSL 544401 (Standard)
- VDSL 547916 & ADSL 544411 will be used for Modem 1.
- VDSL 550e06 & ADSL 551001 will be used for Modem 2.
- VDSL 551506 & ADSL 551501 will be used for Modem 3.
- VDSL 567517 & ADSL 562301 will be used for Modem 4 (G.Vector).
- VDSL 571a17 & ADSL 570111 will be used for Modem 5 (G.Vector) recommended for Netherland ISP - KPN.
- VDSL 572d07 & ADSL 570e01 will be used for Modem 6 (G.Vector) recommended for Netherland ISP - KPN.

(2)For Annex B Model,

- VDSL 548006 & ADSL 544512 (Standard)
- VDSL 542016 & ADSL 535112 will be used for Modem 1.
- VDSL 533d06 & ADSL 535902 will be used for Modem 2.
- VDSL 548006 & ADSL 544512 will be used for Modem 3.
- VDSL 565606 & ADSL 567002 will be used for Modem 4, 5, 6 (G.Vector) recommended for Netherland ISP - KPN.

New Features

- None.

Improvement

- Corrected: CVE-2014-0224 CCS injection vulnerability.

Known Issue

- None

Notes

Modifications

- None