

Release Note for Vigor130 Series

Firmware Version: 3.7.8

Release Date: December 08, 2014

Applied Models:

Vigor130

Note: For DSL models, there will be two folders: STD and VECTOR. The files in VECTOR folder implement a new DSL driver, which supports G.Vectoring on VDSL. If you're using a VDSL line, VECTOR firmware may bring out better performance; however, please consult your ISP to check if G.Vectoring is required. We also provide two versions of Vector firmware to avoid the interoperability issue. You could just try the other one if the one you use cannot synchronize or get the speed that you expected.

- File and Modem Code

(1) For Annex A Model,

- VDSL 548006 & ADSL 544401 (Standard)
- VDSL 547916 & ADSL 544411 will be used for Modem 1.
- VDSL 550e06 & ADSL 551001 will be used for Modem 2.
- VDSL 551506 & ADSL 551501 will be used for Modem 3.
- VDSL 567517 & ADSL 562301 will be used for Modem 4 (G.Vectoring).
- VDSL 571a17 & ADSL 570111 will be used for Modem 5 (G.Vectoring) recommended for Netherland ISP - KPN.
- VDSL 572d07 & ADSL 570e01 will be used for Modem 6 (G.Vectoring) recommended for Netherland ISP - KPN.
- VDSL 567517 & ADSL 562301 will be used for Modem 7 (G.Vectoring) recommended for Germany DT.

(2) For Annex B Model,

- VDSL 548006 & ADSL 544512 (Standard)
- VDSL 542016 & ADSL 535112 will be used for Modem 1.
- VDSL 533d06 & ADSL 535902 will be used for Modem 2.
- VDSL 548006 & ADSL 544512 will be used for Modem 3.
- VDSL 565607 & ADSL 567002 will be used for Modem 4 (G.Vectoring).
- VDSL 565607 & ADSL 567002 will be used for Modem 5, 6 (G.Vectoring) recommended for Netherland ISP - KPN.

- VDSL 567617 & ADSL 567212 will be used for Modem 7(G.Vectoring) recommended for Germany DT.

New Features

- None.

Improvement

- Corrected: Accessed into wrong web page while clicking Cancel in IPv6 configuration page.
- Improved: SSL3 now disabled in favour of TLS by default for SSL tunnels and web management.

Known Issue

- None

Notes

Modifications

- None