Release Note for Vigor2133 Series

Firmware Version:	3.9.3
Release Type:	Normal
Applied Models:	Vigor2133/Vigor2133n/Vigor2133ac/Vigor2133Vac/Vigor2133FVac

Vigor2133 features advanced bandwidth control mechanism such as IP-layer, QoS, NAT Session Limitation, Bandwidth Borrowed, etc., to allow easy, flexible, reliable access control and bandwidth management.

New Features

Support DrayTek VPN Matcher.

Improvement

- Improved: Improve the ACME log message.
- Improved: Improve the privacy of VPN matcher setting.
- Improved: Add a drop down menu of WAN alias IP on System Maintenance >> TR-069 Setting.
- Improved: Add a new 3G connection recovery method for Huawei E3372s-153 dongle.
- Improved: Support IPsec Xauth and IKEv2 EAP authentication made by RADIUS server / LDAP/AD server.
- Corrected: Page display error on WAN>>General Setup.
- Corrected: The issue of VPN connection for remote-dial in client.
- Corrected: The issue of disconnection made by an SSL VPN server.
- Corrected: The issue of unable to establish L2TP/IPsec VPN with Windows 2016 server.
- Corrected: The issue of VoIP RTP TOS value could not be configured correctly by TR-069.
- Corrected: Modifications on menu items for Wireless LAN (2.4 GHz) / Wireless LAN (5 GHz).
- Corrected: The issue of hidden schedule profiles for Wireless LAN (2.4 GHz) / Wireless LAN (5 GHz) >> General Setup under User Mode.

Known Issue

None.