

Release Note for Vigor2710 Series

Firmware Version: 3.2.3

Date: February 18, 2009

Applied Models:

Vigor2710, Vigor2710n, Vigor2710Vn

- File and Modem Code

(1)For Annex A Model,

- " v2710_a_v323" is used for modem code 211801. (Standard)
- " v2710_a1_v323" is used for modem code 211011.
- " v2710_a2_v323" is used for modem code 2121501.
- " v2710_a3_v323" is used for modem code 2211201.

(2)For Annex B Model,

- " v2710_b_v323" is used for modem code 2111112. (Standard)
- " v2710_b1_v323" is used for modem code 2111302.
- " v2710_b2_v323" is used for modem code 2121302.
- " v2710_b4_v323" is used for modem code 214702.
- " v2710_b5_v323" is used for modem code 2121312.
- " v2710_b6_v323" is used for modem code 215202.

New Features

- Support VoIP functions via different protocols, e.g., SIP
- Add new telnet command: voip dsp dtmftonepwr

Improvement

- Improve stability for DSL tx/rx data
- Improve Web login problem

Known Issue

- None

Notes

Modifications

- None