

Release Note for Vigor2760 Series

Firmware Version: 1.2.0.1

Release Date: December 11, 2013

Applied Models:

Vigor2760, Vigor2760n, Vigor2760Vn

DrayTek launches Vigor2760 series – high speed router, perfectly complied with VDSL2/ADSL2/ADSL2+ environment for speed-wanted customers. For more details of the product information, please visit our website on <http://www.draytek.com>. The major feature of such version is that it supports related functions for IPv6.

New Features

- None

Improvement

- Fixed: New added LAN profile in **Network>>LAN** without specified LAN port cannot work normally.
- Fixed: Redirect mechanism in User Management cannot work normally under certain websites.
- Fixed: Redirect mechanism in User Management would cause router reboot sometimes.
- Fixed: Quick Start Wizard cannot work normally.
- Fixed: New added LAN profile cannot be used to access Internet normally.
- Improved: The total profile number will be displayed for each function on the configuration web page.

Known Issue

- Neither "IPsec" nor "GRE over IPsec" supports "More Subnet".
- TACACS+ for Remote Dial-in User can only support PAP authentication (not for CHAP, MS-CHAP, MS-CHAP v2)
- VPN packet triggering can only work for PPTP.
- If the number of http sessions for WCF is over 100 within a short time, the WCF function might be paused till the system excludes the traffic jam condition.

Notes

File and Modem Code

Please open **Network>>WAN>>DSL Mode**. Check the box of **Using custom modem code** to display **DSL firmware for upload**. Click the browse button to choose the suitable modem code and then click **Apply** to use the modem code. Available modem codes for Annex A/Annex B are displayed as follows:

(1)For Annex A Model,

- "v2760001_a.dsl" is used for modem code 548006_544401 (Standard).
- "v2760001_a1.dsl" is used for modem code 532816_533B11
- "v2760001_a2.dsl" is used for modem code 531A16_533011.
- "v2760001_a3.dsl" is used for modem code 532816_533B11-tr114.
- "v2760001_a4.dsl" is used for modem code 541316_540411.
- "v2760001_a5.dsl" is used for modem code 542016_533B11.
- "v2760001_a6.dsl" is used for modem code 547916_544411.

(2)For Annex B Model,

- "v2760001_b.dsl" is used for modem code 548006_544512 (Standard).
- "v2760001_b1.dsl" is used for modem code 533d06_535902.
- "v2760001_b2.dsl" is used for modem code 542016_535112.

Modifications

- Move Remote Management from DSL profile to **System Maintenance >> Management**
- Integrate DHCP Server setting into LAN profile.