

Release Note for Vigor2763 Series

Firmware Version:	4.5.3.1
Release Type:	Important – Review release notes and upgrade if the changes affect your system stability, performance, or security
Applied Models:	Vigor2763, Vigor2763ac, Vigor2763Vac

New Features

- None.

Improvement

- Corrected: An issue causing routers to reboot repeatedly after the firmware upgrade.
- Corrected: An issue where routers randomly reboot multiple times a day due to attacks.
- Corrected: An issue where the firmware upgrade through VigorACS failed under certain conditions.

Known Issue

- None.

File and Modem Code

- "Vigor2763_v4.5.3.1_STD.zip" provides Annex A modem code 77B507_775401, 77B506_775401 and Annex B 779B07_774C12, 779906_774402
- "Vigor2763_v4.5.3.1_MDM1.zip" is used for modem code 77C817_775A11, 77C717_775A11 and Annex B 77C717_775A12, 779B07_774C12