

## Release Note for Vigor2765 Series

Firmware Version:	4.4.3.2
Release Type:	Critical - Upgrade immediately
Applied Models:	Vigor2765, Vigor2765ac, Vigor2765Vac, Vigor2765ax, Vigor2765Vax

Vigor2765 is a VDSL2 35b router which is suitable for speed-wanted customers. With high throughput performance and secured broadband connectivity provided by Vigor2765, you can simultaneously engage these bandwidth-intensive applications, such as high-definition multimedia content, online music, movie streaming and file sharing.

### New Features

- None.

### Improvement

- Improved: Improve Web GUI Security (CVE-2024-23721).
- Corrected: An issue with failure to login web when the WAN was up.

### Known Issue

- For "ax" series model:  
The wireless clients might encounter unexpected trouble (e.g., unable to use the printer on LAN) while accessing into Internet if the hardware acceleration is enabled.  
To skip hardware acceleration for certain devices, the following telnet command can be used:  

```
ppa -E -e 1  
ppa -E -a AA:BB:CC:XX:XX:XX nat|bridge|ipsec
```

### Notes

- Vigor2765ac only supports WDS in wireless 5G.
- This version allows up to 4 LAN subnets to be configured. To avoid continuous system reboot, only the RST file can be used for firmware downgrading.

## File and Modem Code

- "Vigor2765\_v4.4.3.2\_STD.zip" provides Annex A modem code 8B0F07\_8B0701, 8B2607\_8B0B01 and Annex B 8B2607\_8B0B02, 8B2817\_8B0812.
- "Vigor2765\_v4.4.3.2\_MDM1.zip" provides Annex A modem code 8B1117\_8B0701, 8B0F07\_8B0701 and Annex B 8B2817\_8B0812, 8B2607\_8B0B02.
- "Vigor2765\_v4.4.3.2\_MDM2.zip" provides Annex A modem code 8D1917\_8D0C11, 8D1507\_8D0901 and Annex B 8D1917\_8D0C12, 8B2817\_8B0812. Recommended for Australia.
- "Vigor2765\_v4.4.3.2\_MDM3.zip" provides Annex A modem code 77C717\_8D0C11, 8D1507\_8D0901 and Annex B 77C717\_8D0C12, 8B2607\_8B0B02.
- "Vigor2765\_v4.4.3.2\_MDM4.zip" provides Annex A modem code 8D1C17\_8D0E11, 8D1B17\_8D0E11 and Annex B 8D1C17\_8D0E12, 8D1917\_8D0C12.
- "Vigor2765\_v4.4.3.2\_MDM5.zip" provides Annex A modem code 8D1F17\_8D1011, 8D1917\_8D0C11 and Annex B 8D1F17\_8D1012, 8D1917\_8D0C12.